
Onset Computer Corporation Full Cross Arm Kit Packing List (part # M-CAA)

	Qty	\checkmark	ltem(s)
Α	1		Full Cross Arm
В	2		¹ / ₄ -20 x 2 ³ / ₄ " Hex Head Bolts
С	4		¹ / ₄ " Stainless Steel Flat Washers
D	4		¹ /4-20 Nuts
Е	2		¹ / ₂ -20 x 1 ³ / ₄ " Hex Head Bolts
F	1		Mast Plug
G	4		¹ / ₄ " split Lock Washer



Additional Information

Refer to the sensor manual and/or station manual for assembly and operating instructions. For further information, please contact your place of purchase: Onset Computer Corporation or an Authorized Onset Dealer.

5888-C MAN-M-CAA

1.800.561.8187



information@itm.com